# SAFETY DATA SHEET

#### Section 1: Manufacturer's Identification

Product Name: INDUSTRIAL THINNER Product Code: K-1070

Manufacturer's Name: Induron Protective Coatings, LLC Address: 3333 Richard Arrington Blvd. N.

Birmingham, Alabama 35234

Emergency Phone: 1-800-424-9300 Information Phone: (205)324-9584

### Section 2: Composition / Information on Ingredients

## **GHS Ratings:**

| Flammable liquid | 2 | Flash point < 23°C and initial boiling point > 35°C (95°F) |
|------------------|---|--|
| Skin corrosive   | 2 | Reversible adverse effects in dermal tissue, Draize score: |
|                  |   | >= 2.3 < 4.0 or persistent inflammation                    |

2A Eye irritant: Subcategory 2A, Reversible in 21 days

#### **GHS Hazards**

Eye corrosive

| H225 | Highly flammable              |
|------|-------------------------------|
| H315 | Causes skin irritation        |
| H319 | Causes serious eye irritation |

### **GHS Precautions**

| P210           | Keep away from heat/sparks/open flames/hot surfaces - No smoking.            |
|----------------|--|
| P233           | Keep container tightly closed.   |
| P240           | Ground/bond container and receiving equipment.                               |
| P241           | Use explosion-proof electrical equipment.                                    |
| P242           | Use only non-sparking tools.   |
| P243           | Take precautionary measures against static discharge.                        |
| P264           | Wash equipment and contaminated skin thoroughly after handling.              |
| P280           | Wear protective gloves/protective clothing/eye protection/face protection.   |
| P321           | Wash contaminated skin, follow Physcian's instructions for treatment.        |
| P362           | Take off contaminated clothing and wash before reuse                         |
| P302+P352      | IF ON SKIN: Wash with soap and water   |
| P303+P361+P353 | IF ON SKIN (or hair): Remove/Take off immediately all contaminated clothing. |
|                | Rinse skin with water/shower   |
| P305+P351+P338 | IF IN EYES: Rinse continuously with water for several minutes. Remove conta  |
| D000 - D040    | lenses if present and easy to do – continue rinsing                          |
| P332+P313      | If skin irritation occurs: Get medical advice/attention                      |

P337+P313 Get medical advice/attention

P370+P378 In case of fire: Use CO2, water spray, foam, or dry chemical to extinguish.

P403+P235 Store in a well ventilated place. Keep cool

P501 Dispose of contents/container in accordance to approriate regulations and laws.

### Signal Word: Danger





Preexisting skin, eye, and respiratory disorders may be aggravated by exposure to this product. Impaired kidney and liver functions from preexisting disorders may be aggravated by exposure to this product.

Kidney damage may be evidenced by changes in urine output, urine appearance, or edema (swelling from fluid retention). Liver damage may be evidenced by loss of appetite, jaundice and sometimes pain in the upper abdomen

SDS for: K-1070 Page 1 of 5

| Section 3: Hazards Identification |            |                        |  |
|-----------------------------------|------------|------------------------|--|
| Chemical Name                     | CAS number | Weight Concentration % |  |
| Methyl Ethyl Ketone               | 78-93-3    | 90.00% - 100.00%       |  |

#### **Section 4: First Aid Measures**

**INHALATION** - If product solids are inhaled either as dust or in the form of a spray mist, remove the person from exposure immediately. If breathing is difficult, irregular, or has stopped, start resuscitation; call a physician . Administer oxygen if a qualified operator is available.

**EYE CONTACT** - In case of eye contact, flush the eyes with water for fifteen (15) minutes. If contact lenses are worn, quickly remove them, then flush the eyes with water. Have a physician examine the eyes.

**SKIN CONTACT** - In case of skin contact, remove contaminated clothing. Flush the skin with large amounts of water, then wash the skin with soap and water.

**INGESTION** - If material is ingested, seek immediate medical attention. If vomiting occurs spontaneously, keep the head below the hips to prevent aspiration of liquid into the lungs.

Notes to Physician: No data found

#### **Section 5: Fire Fighting Measures**

Flash Point: -4 C (24 F)

LEL: 2.00 UEL:

**EXTINGUISHING MEDIA:** Use carbon dioxide (CO2), "alcohol" foam, dry chemical, or water spray/water fog extinguishing systems.

**UNUSUAL FIRE OR EXPLOSION HAZARDS:** The product vapor is heavier than air and may travel a considerable distance to a source of ignition and flashback.

**HAZARDOUS COMBUSTION PRODUCTS:** See section 10 for a list of hazardous decomposition products for this mixture.

**FIRE FIGHTING:** If evacuation of personnel is necessary, evacuate to an upwind area. Decontaminate personnel and equipment with a water wash-down after fire and smoke exposure.

**FIRE FIGHTING:** If evacuation of personnel is necessary, evacuate to an upwind area. Decontaminate personnel and equipment with a water wash-down after fire and smoke exposure.

### **Section 6: Accidental Release Measures**

**SPILL AND LEAK PROCEDURES:** Spill supervisor - Ensure cleanup personnel wear all appropriate Personal Protective Equipment (PPE), including respiratory protection. Remove all ignition sources. Keep nonessential personnel away from the contaminated area.

**SMALL SPILLS:** Ventilate the contaminated area. Using nonsparking tools, mix the appropriate sorbent into the spilled material. Use an absorbent like sawdust for aqueous, waterborne, and solvent-borne coatings.

Collect the saturated sorbent and transfer it into a covered container. Steel containers are acceptable for all wastes except wastes which contain acid. Use suitable plastic containers for acid-bearing wastes.

Dispose of the waste in compliance with all Federal, state, regional, and local regulations.

**LARGE SPILLS:** Prevent this material from entering sewers and watercourses by diking or impounding the spilled material. Advise authorities if the product has entered or may enter, sewers, watercourses, or extensive land areas.

SDS for: K-1070 Page 2 of 5

Ventilate the contaminated area. Using nonsparking tools, mix the appropriate sorbent into the spilled material. Use an absorbent like sawdust for aqueous, waterborne, and solvent-borne coatings.

Collect the saturated sorbent and transfer it into a covered container. Steel containers are acceptable for all wastes except wastes which contain acid. Use suitable plastic containers for acid-bearing wastes.

### Section 7: Handling and Storage

HANDLING PRECAUTIONS: Wear all appropriate Personal Protective Equipment (PPE). Wear respiratory protection or ensure adequate ventilation at all times as vapors can accumulate in confined or poorly ventilated areas. Use the product in a manner which minimizes splashes and/or the creation of dust. Keep containers closed when not in use. Do not handle or store material near heat, sparks, open flames, or other sources of ignition. Store at room temperatures, i.e., 40 to 95 F (4 to 35 C).

**STORAGE:** Prevent from freezing. Do not store above 120 F (49 C).

Store only in original containers.

#### **REGULATORY REQUIREMENTS:** No data found.

| Section 8: Exposure Controls / Personal Protection |                               |                             |   |  |
|--|-------------------------------|-----------------------------|---|--|
| Chemical Name / CAS No.                            | OSHA Exposure Limits          | ACGIH Exposure Limits       | Other Exposure Limits   |  |
| Methyl Ethyl Ketone<br>78-93-3                     | 200 ppm TWA; 590 mg/m3<br>TWA | 300 ppm STEL<br>200 ppm TWA | NIOSH: 200 ppm TWA;<br>590 mg/m3 TWA<br>300 ppm STEL; 885<br>mg/m3 STEL |  |

ENGINEERING: Ensure processing (curing) ovens are properly vented to prevent the introduction of processing fumes into the workplace. Use explosion-proof equipment and good manufacturing practice.

**VENTILATION:** Use only with adequate ventilation, i.e., ventilation in compliance with occupational exposure limits.

#### ADMINISTRATIVE CONTROLS: No data found.

PROTECTIVE EQUIPMENT: Wear splash goggles. If extra protection is required, wear a face shield over the splash goggles. Face shields are effective only if worn in addition to splash goggles.

Wear a chemical-resistant, butyl-rubber apron and other protective clothing, as deemed appropriate, to avoid skin contact with material.

Wear chemical-resistant gloves (butyl rubber or neoprene). Protective gloves should be inspected frequently and discarded when they exhibit cuts, tears, pinholes, or signs of excessive wear.

CONTAMINATED EQUIPMENT: Dispose of the waste in compliance with all Federal, state, regional, and local regulations.

### **Section 9: Physical and Chemical Properties**

This mixture typically exhibits the following properties under normal circumstances:

| Appearance: N/A Vapor Pressure: 75.8 mmHg  Vapor Density: 2.4  DENSITY 6.71  Freezing point: N/A  Boiling range: 80°C  Evaporation rate: N/A  Odor: N/A  Odor threshold: N/A  Melting point: N/A  Solubility: N/A  Flash point: 24 F,-4 C  Flammability: N/A | Viscosity: N/A            | Coating VOC Lb/Gal 6.71 |
|--|---------------------------|-------------------------|
| Vapor Density: 2.4 pH: N/A  DENSITY 6.71 Melting point: N/A  Freezing point: N/A Solubility: N/A  Boiling range: 80°C Flash point: 24 F,-4 C   | Appearance: N/A           | Odor: N/A               |
| DENSITY 6.71  Melting point: N/A  Freezing point: N/A  Solubility: N/A  Boiling range: 80°C  Flash point: 24 F,-4 C  | Vapor Pressure: 75.8 mmHg | Odor threshold: N/A     |
| Freezing point: N/A  Boiling range: 80°C  Flash point: 24 F,-4 C   | Vapor Density: 2.4        | pH: N/A                 |
| Boiling range: 80°C Flash point: 24 F,-4 C   | DENSITY 6.71              | Melting point: N/A      |
|  | Freezing point: N/A       | Solubility: N/A         |
| Evaporation rate: N/A Flammability: N/A  | Boiling range: 80°C       | Flash point: 24 F,-4 C  |
| ·  | Evaporation rate: N/A     | Flammability: N/A       |

**Explosive Limits: N/A** 

Printed: 10/18/2016 at 8:36:02AM

## Partition coefficient (n- N/A octanol/water):

Decomposition temperature: N/A

Autoignition temperature: N/A

### Section 10: Stability and Reactivity

Stability:

**STABLE** 

Components of this mixture are incompatible with the following materials:

This mixture is likely to exhibit the following combustion products:

Hazardous polymerization will not occur.

## **Section 11: Toxicological Information**

#### **Mixture Toxicity**

Oral Toxicity LD50: 2,483mg/kg Dermal Toxicity LD50: 5,000mg/kg

Routes of Entry:

Ingestion

Exposure to this material may affect the following organs:

Eyes **Central Nervous System** Skin **Respiratory System** 

**Effects of Overexposure** 

Carcinogenicity: The following chemicals comprise 0.1% or more of this mixture and are listed and/or classified as carcinogens or potential carcinogens by NTP, IARC, OSHA (mandatory listing), or ACGIH (optional listing).

**CAS Number** Description % Weight Carcinogen Rating

### Section 12: Ecological Information

Ecological information: No data found.

**Component Ecotoxicity** 

Methyl Ethyl Ketone 96 Hr LC50 Pimephales promelas: 3130 - 3320 mg/L [flow-through]

48 Hr EC50 Daphnia magna: >520 mg/L; 48 Hr EC50 Daphnia magna: 5091

mg/L; 48 Hr EC50 Daphnia magna: 4025 - 6440 mg/L [Static]

#### **Section 13: Disposal Considerations**

As the US EPA, state, regional, and other regulatory agencies may have jurisdiction over the disposal of your facility's hazardous waste, it is incumbent upon you, the hazardous waste generator, to learn of and satisfy all the requirements which affect you. Dispose of the hazardous waste at a properly licensed and permitted disposal site or facility. Ensure conformity to all applicable hazardous waste disposal regulations.

The US EPA Hazardous Waste Numbers which follow are applicable to this unadulterated product if the product enters the "waste stream." Refer to Title 40 of the Code of Federal Regulations, Part 261 (40 CFR 261). This part of the Code identifies solid wastes which are subject to regulation under various sections of the Code and which are subject to the notification requirements of Section 3010 of the Resource Conservation and Recovery Act (RCRA).

### **Section 14: Transport Information**

# Section 14 - Transport Information

SDS for: K-1070 Page 4 of 5

| <b>Agency</b> | Proper Shipping Name | UN Number | Packing Group | <b>Hazard Class</b> |
|---------------|----------------------|-----------|---------------|---------------------|
| DOT           | METHYL ETHYL KETONE  | 1193      | II            | 3                   |
| IATA          | METHYL ETHYL KETONE  | 1193      | II            | 3                   |

### 15: Regulatory Information

MASSACHUSETTS RIGHT TO KNOW 78-93-3 Methyl Ethyl Ketone 90 to 100 %

NEW JERSEY RIGHT TO KNOW 78-93-3 Methyl Ethyl Ketone 90 to 100 %

PENNSYLVANIA RIGHT TO KNOW 78-93-3 Methyl Ethyl Ketone 90 to 100 %

CHEMICAL LIST FOR SARA 311/312 78-93-3 Methyl Ethyl Ketone

Country Regulation All Components Listed


### **EU Risk Phrases**

### **Safety Phrase**


- None

### 16: OTHER INFORMATION

## **Hazardous Material Information System (HMIS)**



## National Fire Protection Association (NFPA)



Reviewer Revision

Date Prepared: 10/18/2016

SDS for: K-1070 Page 5 of 5